



*Route to Ken, then
file.*

RECEIVED

August 27, 1993

SEP 01 1993

Ms. Pamela Grubaugh-Littig
Permit Supervisor
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84140-1203

Copy
DIVISION OF
OIL, GAS & MINING

**RE: MAINTENANCE ALONG THE C2 CONVEYOR, PACIFICORP, DEER CREEK
MINE, ACT/015/018, EMERY COUNTY, UTAH**

Dear Pamela:

#2

Due to recent isolated thunder showers at the Deer Creek Mine, it is necessary to remove accumulated sediment from the backside of the C2 conveyor. The sediment is being removed by a trackhoe, placed into a dump truck and hauled to the Waste Rock Facility for disposal.

The lower end of the C2 conveyor has been a maintenance problem for the mine, requiring routine maintenance following most larger precipitation events. While the crews are cleaning the above mentioned sediment from the area, we are planning to upgrade the existing culvert at IU 180 from a 24 inch to a 30 inch culvert. The additional capacity of the 30 inch culvert will help lower maintenance frequency of this area.

If you have any questions or concerns, please contact Guy Davis or me at 653-2312.

Sincerely,

Val Payne
Sr. Environmental Engineer

cc: Steve Kochevar
Morgan Moon