



*[Handwritten signature]*  
Page 1 of 3

- Partial
- Complete
- Exploration

Inspection Date: July 20, 1993  
 Time: 8:15  am  pm to 2:00  am  pm  
 Date of Last Inspection: 6/9/93

Mine Name: Deer Creek County: Emery Permit Number: Act 10151010  
 Permittee and/or Operator's Name: Pacifi Corp  
 Business Address: P.O. Box 1005, Huntington, Utah 84528  
 Type of Mining Activity:  Underground  Surface  Prep. Plant  Other  
 State Official(s): Bill Malenak  
 Company Official(s): Karl Hauskeeper  
 Federal Official(s): N/A

Weather Conditions: Clear / Dry Mine Site / Wood Ticks!  
 Existing Acreage: Permitted-14668 Disturbed-56 Regraded-     Seeded-     Bonded-56  
 Increased/Decreased: Permitted-     Disturbed-     Regraded-     Seeded-     Bonded-      
 Status:  Exploration /  Active /  Inactive /  Temporary Cessation /  Bond Forfeiture  
 Reclamation ( Phase I /  Phase II /  Final Bond Release /  Liability      Year)

**REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS**

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

inspection report

INSPECTION REPORT COMMENTS

Permit No. Act/015/018

Inspection Date 7/20/93

Please number comments to correspond with topics on previous page.

General Comments Partial inspection covered the mine site, waste rock area, and did not include Rilda Canyon area.

Permit The mag-clay storage area has been approved as an amendment. No on the ground work has started on this project. Also the permittee submitted an amendment for temporary coal waste storage on the current storage pad.

Diversion The "Tipple Access Road Ditch" was discussed in the June inspection. The ditch appeared to have a large amount of seprap installed recently. Requested the operator to check the field conditions with the design, even though no evidence of failure was observed.

The operator check with designs were made as follows:

Upper Ditch -- Design, width 8'1/2', depth 1/2' to 1' (Typical)

-- Measurements 8'x8", 5'x6", 3'x10", 6'x7"

Lower Ditch -- Design, width 3', depth 8" (depth was scaled from drawing)  
3'x7"

The operator is removing a large rock on the upper ditch where the width was measured at 3', even though no short circuiting was observed. Also the rock was located

Copy of report mailed to \_\_\_\_\_

Copy of report given to \_\_\_\_\_

Inspector's signature \_\_\_\_\_ No. \_\_\_\_\_

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act/015/018

Inspection Date 7/20/93

Please number comments to correspond with topics on previous page.

at the upper segment of the ditch and the flow in this segment because of the dendritic drainage pattern was less than half of the flow on the ditch lower segment.

Coal Mine Waste. New lift started on the waste rock site. Some non-coal waste was segregated from the coal waste. The operator stated this material will be removed to the non-coal waste disposal area.

Explosives. Checked powder and caps storage area. The containers were in a side canyon below the mine. Both containers had double locks.

Roads. The road along the lower beltline had recently been graded. The water bars that control road drainage were observed.

Other Transportation Facilities. The beltline that transports coal to the coal chute was recently cleaned i.e., coal spillage under the beltline.

Copy of report mailed to PC/Karl Houskeeper; OSU/MoPetta; DOGM/Joe Helfrich

Copy of report given to filed PFO

Inspector's signature Dr. J. Chalovich No. 26

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE