



inspection report

- Partial
- Complete
- Exploration

Inspection Date: April 6, 1993  
 Time: 9 : 00  am  pm to 11 : 30  am  pm  
 Date of Last Inspection: 3/19/93

Mine Name: Deer Creek County: Emery Permit Number: Act/015/018

Permittee and/or Operator's Name: Pacy Corp

Business Address: P.O. Box 10051 Huntington, Utah 84528

Type of Mining Activity:  Underground  Surface  Prep. Plant  Other

State Official(s): Bill Malencik

Company Official(s): Karl Houskeeper, John Christensen

Federal Official(s): N/A.

Weather Conditions: Windy, clear & cold

Existing Acreage: Permitted- 14668 Disturbed- 56 Regraded- \_\_\_\_\_ Seeded- \_\_\_\_\_ Bonded- 56

Increased/Decreased: Permitted- \_\_\_\_\_ Disturbed- \_\_\_\_\_ Regraded- \_\_\_\_\_ Seeded- \_\_\_\_\_ Bonded- \_\_\_\_\_

Status:  Exploration /  Active /  Inactive /  Temporary Cessation /  Bond Forfeiture  
 Reclamation ( Phase I /  Phase II /  Final Bond Release /  Liability \_\_\_\_\_ Year)

**REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS**

**Instructions**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) <u>4/6/93</u> (date)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act/015/018

Inspection Date April 6, 1993

Please number comments to correspond with topics on previous page.

Permit. Permit for Deer Creek was approved by 2/15/91. The permit supervisor on 3/1/93 notified the permittee of the mid term and issues. The only issue involved amending the impoundment quarterly and annual reports PAP commitments so they would square with the Utah coal mining regulations. Amendment was submitted 4/2/93 and is under review by the Division.

Sign & Markers. The operator advised me that they would make minor change in the ID sign by eliminating the word reclamation preceding the word permit.

Sediment Pond. The pond contained runoff, the lower end was ice covered and the upper was void of ice.

Division. One diversion was repaired during the inspection. The outlet of a culvert on the main pad below the beltline was crushed. Runoff still flowed through the culvert. The culvert was repaired before the inspection closeout.

Emery County road department had signed a piping hole in their road drainage ditch. The hole was 3' deep and about 5' wide. The road department is in the process of

Copy of report mailed to \_\_\_\_\_

Copy of report given to \_\_\_\_\_

Inspector's signature \_\_\_\_\_ No. \_\_\_\_\_

WHITE-DOG M YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Ad/015/018

Inspection Date 4/6/93

Please number comments to correspond with topics on previous page.

repairing the road. The piping hole is within the road right of way and is located about 0.1 of a mile below the mine control point (former gate).

The undisturbed drainage by the main fan while fully functional should be cleaned of rocks & ice.

Roads The road adjacent to the beltline/coal chute needs to have a berm removed. The berm was the result of snow removal and the drainage is sheet flow and not by a designed diversion.

Other In connection with facing-up the portals a small bench was created prior to the enactment of SMCPA. Rocks, soil material & one tree has fallen and covered the bench in one area and rocks have partially covered the bench in another area. The operator said they would remove the rocks so they would not have a chance to impact the surface operations in the immediate area.

Copy of report mailed to PacificCorp/Karl Houskeeper; OSM/Brian Smith; DOGM/Doc Helbach

Copy of report given to filed PFO

Inspector's signature Jim J. MacLennan

No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

4/7/93