

015/018 #2

0074

One Utah Center
201 South Main, Suite 2100
Salt Lake City, Utah 84140-0021
(801) 220-2000

Val E. Payne
Sr. Env. Engineer
PacifiCorp Field Office
P. O. Box 1005
Huntington, UT 84528
(801) 653-2312
FAX (801) 653-2479



April 22, 1994

Utah Coal Regulatory Program
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

APR 25 1994
DIV. OF OIL, GAS & MINING

Attn. Pamela Grubaugh-Littig

**RE: TIRE STORAGE DOCK AMENDMENT, PACIFICORP, DEER CREEK MINE,
ACT/015/018-94D, EMERY COUNTY, UTAH**

Dear Ms. Grubaugh-Littig:

Pacificorp requests that an amendment be granted to allow construction of a Tire Storage Dock at the Deer Creek Mine. Three 8 1/2" X 11" design drawings for the dock and cover are enclosed. The added reclamation cost for the project, as detailed below, is \$3,348.25, which equals 0.17% of the bond. The total accumulated reclamation costs since the last reclamation cost adjustment is \$3,348.25, the current amendment only. The accumulated reclamation cost is < 5% of the current \$2,000,000 bond, therefore no adjustment to the bond is required per page 4-65 of the approved permit.

RECLAMATION COSTS

PRODUCTION

(1 Round Trip/hr) (10yd³/Trk) (2 Trks)
(150 yd³ of Material) ÷ (20 yd³/hr)

TOTAL

20 yd³/hr
7.5 hrs.

DOCK LABOR COSTS

(3 men) (7.5 hrs.) (\$29.10/hr.)
(1 forman) (7.5 hrs.) (\$32.25/hr.)

\$654.75
241.90

SUBTOTAL

\$896.50

FOOTAGE CONVERSION

Single sided 225 ft.
Convert footage to sections using 20 ft./section
225 ft. ÷ 20 ft./sec. = 11.25 sections

COVER LABOR COSTS/20 FT.

Tin (2 men) (.25 hrs.) (\$29.10/hr.)
Purlins (2 men) (.25 hrs.) (\$29.10/hr.)
Trusses (2 men) (.5 hrs.) (\$29.10/hr.)

\$14.55
14.55
29.10
\$58.20

SUBTOTAL

(\$58.20) (11.25 sec.)

\$654.75

TOTAL LABOR

\$654.75 + \$896.50

\$1,551.25

EQUIPMENT COSTS

(2 Rock Trucks) (7.5 hrs.) (\$53.30/hr./trk)	\$799.50
(235 Trackhoe) (7.5 hrs.) (\$133.00/hr.)	<u>997.50</u>

SUBTOTAL \$1,797.00

GRAND TOTAL
\$1,551.25 + \$1,797.00 \$3,348.25

Upon completion the dock will be identified on an updated Surface Facilities Map DS202E, Packet 3-9. Storage docks are identified on page 3-31, Material Storage Area, therefore no text additions are required. However, page 3-54 has been revised (4/22/94) to reflect construction year for various storage docks.

Your help is appreciated. If there are any questions, please call Guy Davis or me at 653-2312.

Sincerely,



Val E. Payne
Sr. Env. Engineer

gd/

cc: Morgan Moon, w/o attachments
John Christensen, " "