


0066



PO Box 310  
Huntington, Utah 84528

January 30, 1997

Utah Coal Regulatory Program  
Division of Oil, Gas and Mining  
451 East 400 North  
P.O. Box 156  
Price, Utah 84501



Attention: Mr. Pete Hess

**Re: AMENDMENT: UPDATE MAPS, CONVERT TO AUTOCAD, REVISE APPENDIX A IN VOLUME 9 - HYDROLOGIC SECTION, PACIFICORP, DEER CREEK MINE ACT/015/018, COTTONWOOD MINE ACT/015/019, DES-BEE-DOVE MINES ACT/015/017, EMERY COUNTY, UTAH**

#2

97B

**UPDATE MAPS IN VOLUME 4, PACIFICORP, DEER CREEK MINE ACT/015/018**

PacifiCorp, by and through its wholly-owned subsidiary, Energy West Mining Company ("Energy West") as mine operator, herewith submits an amendment to update Volume 9 - Hydrologic Section, Deer Creek Mine ACT/015/018, Cottonwood Mine ACT/015/019, Des-Bee-Dove Mines ACT/015/017 and Volume 4 of the Deer Creek Mine ACT/015/018 as follows:

**Volume 9 - Hydrologic Section,**

- Replace Maps:**
- HM-1**
  - HM-2**
  - HM-3**
  - HM-4**
  - HM-5**

Map HM-1 through HM-5 have been converted to electronic format. In addition to the format change, two additional surface monitoring sites were added to PacifiCorp's hydrologic monitoring program in Mill Fork Canyon, (formally monitored by Mountain Coal Company), to coincide with the Deer Creek Mine "North Rilda Area" permit modification to be submitted on February 3, 1997. Maps HM-2 and HM-3 have been

Huntington Office:  
(801) 687-9821  
Fax (801) 687-2695  
Purchasing Fax (801) 687-9092

Deer Creek Mine:  
(801) 381-2317  
Fax (801) 381-2285

Cottonwood Mine:  
(801) 748-2319  
Fax (801) 748-2380

January 30, 1997  
Page Two

updated to reflect the current mine development as of December 01, 1996 and monitoring location status.

**Replace Appendix A**

Appendix A was updated to include the additional surface monitoring sites in Mill Fork Canyon.

**Volume 4 - Deer Creek Mine ACT/015/018:**

**Replace Maps:**

**3-6** ( Drawing CM-10894-DR ) Replaced by **3-6** (Drawing CM-10899-DR)  
**3-7** ( Drawing CM-10895-DR ) Replaced by **3-7** (Drawing CM-10900-DR)

Maps 3-6 and 3-7 were updated to include the revised R<sub>2</sub>P<sub>2</sub>.

In conjunction to these updates the Table of Contents of Volume 1, has been updated, therefore find the following pages as revised:

Table of Contents, page 4, located in Volume 5, maps 3-6 and 3-7 changes.  
Table of Contents, page 4.1, changing the typing error, under Volume 6, 3-18,  
Access Toad to Access Road.

Please find attached seven copies each of the above cited amendments.

Please return a copy stamped with your approval.

If you have any questions, please contact me at 687-4720.

Sincerely,



Charles A. Semborski  
Geologic/Permitting Supervisor

cc: Carl Pollastro  
Dick Northrup  
Dept. file