

0060

PLC

File: 1015018

8/15/08
J. Boyer

Forest Supervisor's Office
And
Price Ranger District
599 West Price River Drive
Price, Utah 84501

FAX Transmittal



Phone: (435) 637-2817
FAX: (435) 637-4940



To: JIM SMITH
From: KARL BOYER 435-636-3551
Subject: HYDROLOGY DOCUMENTS
Total Pages (including cover page): 2

Comments:

RECEIVED
AUG 27 2002
DIVISION OF
OIL, GAS AND MINING

BIBLIOGRAPHY

1. Vaughn Hansen Associates, August 1977, Water Quality and Hydrologic Study in Vicinity of Huntington Creek Mine No.4 and Little Bear Spring
2. Utah Geological & Mineral Survey, January 1984, Effects of Coal Mining at Huntington Canyon No.4 Mine on Little Bear Spring, Emery County
3. Vaughn Hansen Associates, 1984, Hydrologic Conditions in Huntington Canyon No.4 Mine
4. Lines, Gregory, United States Geological Survey, 1985, U.S. Geological Survey Water Supply Paper 2259, The Ground-Water System and Possible Effects of Underground Coal Mining in the Trail Mountain Area, Central Utah
5. Hansen Allen & Luce Inc., March 1997, Probable Hydrologic Consequences Evaluation of LBA 11
6. Mayo and Associates, March 1997, Supplemental Hydrogeologic Information For LBA 11
7. Water Technology and Research, Inc., 1998, Aqua Track Survey, Little Bear Springs Study
8. Water Technology and Research, Inc., 1999, Aqua Track Survey, Little Bear Springs Study
9. Mayo and associates, LC, January 2001, Investigation of the Potential for Little Bear Spring Recharge in Mill Fork Canyon, Emery County, Utah
10. Sunrise Engineering, Inc., 2001, Aqua Track Survey, Little Bear Spring
11. Mayo and Associates, LC, November 2001, Determination of the Recharge Location of Little Bear Spring by Means of Flourescent Dye Tracing