



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

PHL
by
JD
OK

INSPECTION REPORT

Partial XXX Complete ___ Exploration ___
Inspection Date: 07/29/2002 Time: 10:00am-2:00pm
Date of Last Inspection: 06/20/2002

Mine Name: Deer Creek Mine County: Emery Permit Number: C/015/018
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Company Official(s): Dennis Oakley
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 80's, Sunny
Type of Mining Activity: Underground XXX Surface ___ Prep Plant ___ Other ___
Existing Acreage: Permitted 19010 Disturbed 95.79 Regraded ___ Seeded ___
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter- April, May, June); AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: 07/29/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has several permitting actions at the Division. These are 1) Revision to Reclamation Plan, 2) Mill Fork Lease, 3) Volume 1, General Content, and 4) Permit Area Change (65.7 acres). The permit area change and Volume 1 will be approved the first week of August.

3. TOPSOIL

The topsoil pile at the waste rock site was inspected with no signs of erosion from water or wind.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and complied with the requirements in the Mining and Reclamation Plan. These diversions met the R645 performance standards.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The refuse sediment pond was also inspected with no signs of hazardous conditions existing. This sediment pond did not contain water and is unlikely to discharge in the near future.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The catch basins were constructed as designed. No water was within these structures.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has been entering water sampling information in to the Electronic Data Base.

The permittee has been notified that in the future the Division will not accept "No Access" to a water-monitoring site as meeting their water monitoring requirements.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS


The refuse piles were inspected and no hazardous conditions were noticed.

8. NONCOAL WASTE

The disturbed area at the mine is generally clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new construction at the mine had taken place.

Inspector's Signature:  Date: August 2, 2002
Stephen J. Demczak #39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.
cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office
O:\015018.DER\Compliance\2002\p_0729.doc