

From: "Oakley, Dennis" <dennis.oakley@pacificorp.com>
To: "'Jim Smith'" <JIMDSMITH@utah.gov>
Date: 1/8/03 3:34PM
Subject: RE: Deer Creek discharge

The flow rate on the DMR should be 0.22 not 2.2. Thanks for finding this error.

Dennis Oakley
Environmental Engineer

Energy West Mining Company
15 North Main Street
Huntington, Utah 84528
Phone: 435.687.4825
Fax: 435.687.2695
E-mail: dennis.oakley@pacificorp.com

-----Original Message-----

From: Jim Smith [mailto:JIMDSMITH@utah.gov]
Sent: Wednesday, January 08, 2003 8:08 AM
To: dennis.oakley@pacificorp.com
Subject: RE: Deer Creek discharge

Dennis,

Another one to check. November 2001 DMR report for Deer Creek UT0023604-001 shows Avg and Max discharge of 2.2 mgd, equal to 1,527 gpm: this is a lot higher than the preceding or following months. The DMR says there was snow melt in Nov., but are the reported DMR flows correct? The quarterly report shows 153 gpm (which is still high for this site but not extreme).

JIM

James D. SMITH
jimdsmith@utah.gov <mailto:jimdsmith@utah.gov>
801 538 5262

This email is confidential and may be legally privileged.

It is intended solely for the addressee. Access to this email by anyone else, unless expressly approved by the sender or an authorized addressee, is unauthorized.

If you are not the intended recipient, any disclosure, copying, distribution

or any action omitted or taken in reliance on it, is prohibited and may be unlawful. If you believe that you have received this email in error, please contact the sender, delete this e-mail and destroy all copies.

=====