



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Company, Name/Title. Row 1: Dennis Oakley, Environmental Engineer. Row 2: OGM Steve Demczak, Environmental Scientist III

Inspection Report

Table with 2 columns: Field, Value. Fields: Permit Number (C0150018), Inspection Type (COMPLETE), Inspection Date (Friday, June 16, 2006), Start Date/Time (6/16/2006 10:00:00 AM), End Date/Time (6/16/2006 2:00:00 PM), Last Inspection (Thursday, May 25, 2006)

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 90's

InspectionID Report Number: 995

Accepted by: pgrubaug
7/11/2006

Permittee: PACIFICORP
Operator: ENERGY WEST MINING CO
Site: DEER CREEK MINE
Address: PO BOX 310, HUNTINGTON UT 84528
County: EMERY
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Values: 22,213.70 (Total Permitted), 84.34 (Total Disturbed), Phase I, Phase II, Phase III

Mineral Ownership

- Checked: Federal, State, Fee. Unchecked: County, Other

Types of Operations

- Checked: Underground. Unchecked: Surface, Loadout, Processing, Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions:

- 1) During entry development if sustained quantities of groundwater are encountered which are greater than 5 gpm from a single source...
2) Vehicle access will not be allowed in Rilda Canyon from December 1 to April 15...
3) PacifiCorp will submit water quality data for the Deer Creek Mine in an electronic format through the EDI web site.
-The permittee is meeting these conditions at this time.
-Permitting Actions - New Surface Facilities in Rilda Canyon - Mining Plan Approval was issued on December 21, 2005, the state permit was issued on December 1, 2005.
-Violations: None

Inspector's Signature:

Date Tuesday, June 27, 2006

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permittee will be submitting information in Chapter 1 for the permit transfer that had taken place.

3. Topsoil

The topsoil pile at the waste rock site was inspected. The permittee notified me that a rain storm on June 9 caused sediment build-up of silt fences. The permittee was told to have the silt fences fixed by June 23, 2006. I inspected the fences on June 23rd and the fences were functioning as designed.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and were functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The permittee had taken the first quarter inspection of the sediment ponds. No hazardous conditions were reported.

4.c Hydrologic Balance: Other Sediment Control Measures

The permittee will be working on silt fences at the waste rock site. I inspected for sediment control at Rilda Canyon. The sediment control is in the road ditch using straw bales and silt fences along the stream. No problem was noticed at this time.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected with no hazardous conditions reported. This report was P.E. certified.

8. Noncoal Waste

The mine site was clear of non-coal waste material.

21. Bonding and Insurance

The insurance policy will expire on August 28, 2005. Assoc Electric and Gas Ins. Service Ltd is affording insurance coverage.