

0070

From: "Semborski, Chuck" <Charles.Semborski@PacifiCorp.com>
To: "Jim Smith" <jimsmith@utah.gov>
Date: 10/30/2007 1:16 PM
Subject: RE: Ground Water Seepage in Rilda Canyon

Jim Smith
10/31/07

Yes, we have established a new monitoring point in Rilda Canyon below the seep area.

Mine Site 4
Site Name North Rilda Ridge Star Point Fractures
Location: GPS coordinates will be provided later this week

Site Number: Jim please email me a new site number

Thanks

Chuck Semborski
Manager of Exploration and Geology
Interwest Mining Company
P.O. Box 310
Huntington, Utah 84528
Phone:
Work - (435)687-4720
Cell - (435)650-5355

-----Original Message-----

From: Jim Smith [mailto:jimsmith@utah.gov]
Sent: Monday, October 29, 2007 3:07 PM
To: Semborski, Chuck
Cc: Thomas W Lloyd; Pam Grubaugh-Littig
Subject: Re: Ground Water Seepage in Rilda Canyon

Chuck,

Thank you for this information.

Are the water quality data to be entered into the database? Is there a map of these locations?

JIM

>>> "Semborski, Chuck" <Charles.Semborski@PacifiCorp.com> 10/25/2007 2:19 PM >>>
Tom Lloyd

Recently you inquired whether the seeps located along the Emery County road in Rilda Canyon were related to the Deer Creek Mine workings located in North Rilda Ridge. To give you a history of mining in this area, Energy West completed mining in the North Rilda Ridge Area (Hiawatha seam [8th Right longwall panel]) in August 2004. Seals isolating this area were installed in February 2005.