

Thomas W Lloyd
 1/7/2008
 JK

From: Thomas W Lloyd <twlloyd@fs.fed.us>
To: "Fleck, Ken" <Kenneth.Fleck@PacifiCorp.com>
Date: 1/7/2008 10:25 AM
Subject: Re: Rilda Canyon Left Fork Emergency Road Use
Attachments: Rilda Left Fork Intake Cave #2.doc

CC: "Semborski, Chuck" <Charles.Semborski@PacifiCorp.com>, "Oakley, Dennis" ...
 Ken and Pam,

Fosest Service has no problem with authorizing another one time exception to the timing restriction for use of the road in the Left Fork of Rilda Canyon given serious conditions described below.


Tom Lloyd
 North Zone Minerals Manager
 Manti LaSal National Forest
 Office: 435-636-3596
 Cell: 435-749-1658

"Fleck, Ken"
 <Kenneth.Fleck@PacifiCorp.com>
 To
 "Thomas W Lloyd"
 01/07/2008 09:08 AM <twlloyd@fs.fed.us>, "Pam
 Grubaugh-Littig"
 <PAMGRUBAUGHLITTIG@utah.gov>
 cc
 "Snow, H. Earl"
 <Harry.Snow@PacifiCorp.com>,
 "Oakley, Dennis"
 <Dennis.Oakley@PacifiCorp.com>,
 "Semborski, Chuck"
 <Charles.Semborski@PacifiCorp.com>,
 "LaFrentz, Larry"
 <Larry.Lafrentz@PacifiCorp.com>
 Subject
 Rilda Canyon Left Fork Emergency
 Road Use

Tom and Pam,

Deer Creek Mine has experienced another serious roof fall in the Left Fork intake portal in Rilda Canyon. This fall occurred yesterday (Sunday, January 6) just inside the mine from the cave that occurred last March (see attached map). The cave, which is along our main intake roadway, crushed

LEFT
FORK
RILDA
CANYON



CAVE SATURDAY
MORNING
3/24/07

CAVE SUNDAY
1/6/08

