



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

Outgoing  
C0150018  
#3585  
OK

August 19, 2010

Kenneth Fleck  
Manager of Geology and Environmental Affairs  
Energy West Mining Company  
P.O. Box 310  
Huntington, Utah 84528

Subject: Amendment to Update MRP, PacifiCorp, Deer Creek Mine, Permit C/015/0018,  
Task ID #3585

Dear Mr. Fleck:

The above-referenced amendment to the Deer Creek Mine MRP has been reviewed and found deficient. The Division requires that your application be modified to address the deficiencies that are listed in the attachment to this letter, in accordance with R645-300-131.100. The plans as submitted are denied. Please resubmit the entire application (including redline/strike-out and C1/C2 forms) by no later than September 16, 2010.

Each deficiency includes the initials of the member of the Division who wrote it so that your staff can directly communicate with that individual should any questions arise relative to the preparation of your response.

If you have any questions, please feel free to call me at (801) 538-5362 or the appropriate member of the Division staff.

Sincerely,

James D. Smith  
Permit Supervisor

JDS/sqs

Enclosure

cc: Price Field Office

O:\015018.DER\FINAL\WG3585\WG3585.JDS.DEFICIENCY.DOC

**Deficiency List**  
**Task No. 3585**  
**Amendment to Update MRP**

The members of the review team include the following individuals:

JDS     Jim Smith  
PWB     Priscilla Burton

**R645-301-742.320, -330**, Because some values for ditch and culvert lengths in Tables 6, 7, 8, and 9 in Volume 11B don't match culvert and ditch lengths shown on Map 700-2, the Permittee must assure that correct lengths have been used to calculate the slope values which were input into the ditch and culvert design calculations in Appendices 2 and 3 of Volume 11B, in particular for UD-5, DD-3, DD-4, and UC-2. As needed, revise Tables 6, 7, 8, and 9 in Volume 11B to incorporate accurate ditch and culvert lengths. [JDS]

**R645-301-422**, On page 4, under Section R645-301-422, the application indicates that an air quality approval order remains outstanding for the Rilda construction. Please provide the current Approval Order number and date [PWB].

**R645-301-121.200**, Map 500-4 Sheet 3 of 4 refers to Map 500-3 for cross-section locations, however Map 500-3 does not show cross-sections. Please provide cross-section locations on Map 500-3. On Map 500-4 Sheet 3 of 4 please include the dashed line in the legend. [PWB]