



United States Department of the Interior  
OFFICE OF SURFACE MINING  
Reclamation and Enforcement  
BROOKS TOWERS  
1020 15TH STREET  
DENVER, COLORADO 80202

MWJ JWS  
Route & File  
120  
R. 8/8  
8/4

July 2, 1980 #7

Mr. Ron Daniels  
Coordinator of Mined Land Development  
Department of Natural Resources  
1588 West North Temple  
Salt Lake City, Utah 84116

Dear Mr. Daniels:

Enclosed please find a copy(s) of on-site inspection report. The inspection was conducted within Cottonwood Mine during the period of June 4, 1980.

If you have any questions or problems, please contact this office.

Sincerely,


Thomas E. Ehmett, Acting Chief  
Division of Inspection & Enforcement

REGION V ON-SITE INSPECTION REPORT

UTAH POWER AND LIGHT COMPANY  
COTTONWOOD MINE  
P.O. Box 899  
Salt Lake City, Utah 84110

DATE: June 4, 1980  
TIME: 1:30 p.m.  
WEATHER: Sunny and warm  
COUNTY & STATE: Emery County, Utah  
COMPANY OFFICIALS: Carl Gurr and Larry Guyman  
STATE OFFICIALS: Joe Helfrich and Mary Kay Stein  
OSM OFFICIALS: Larry Damrau and Dan Martinez  
STATE PERMIT NO: None  
MSHA I.D. NUMBER: None

A follow-up inspection was conducted to evaluate the remedial action taken as required under Violation Number 3 of Notice of Violation Number 80-5-3-3 for failure to post mine and permit identification signs. A sign was posted, with the required information, adjacent to the haulroad/access road within Cottonwood Canyon. The violation was terminated following the inspection.

  
LARRY DAMRAU  
RECLAMATION SPECIALIST