

June 18, 1980

Inspection Memo  
To Coal File:

#7

RE: Cottonwood Canyon Portal  
Utah Power and Light Co.  
ACT/015/027  
Emery County, Utah

On June 4, 1980 the above mentioned operation was visited by Joe Helfrich, Lee Spencer and Mary Kay Stein from the Division and Lary Damrau and Dan Martinez from the Office of Surface Mining.

The purpose of the trip was to terminate the following federal violation issued during the citizens complaint inspection dated February 22 and 27. Violation number three; Rule MC 717.12 (a) failure to post adequate signs or markers at public access points to the permit area. The above mentioned violation was terminated by Lary Damrau on June 4, 1980 as signs were posted above and below the permit area along the Forest Service Road.

In reference to the material excavated from the construction from the sedimentation pond that was deposited between Cottonwood Creek and the Forest Service access road, inspector Damrau issued an abatement date for removal of material to predesignated subsoil stockpile area as of July 7, 1980.

Lee Spencer, Reclamation Engineer, Division, inspected the Cottonwood Portal in reference to the slope stabilization report submitted to the Division, May 13, 1980, See Cottonwood Portal Stability of Waste Dumps, Memo dated June 9, 1980.

No violations were issued.



MARY KAY STEIN  
RECLAMATION OFFICER

MKS/lml

cc: Murray Smith; OSM Denver

Note: For statistics see Beaver Creek

Coal Company, Gordon Creek #2 Mine, dated June 16, 1980.