

### Document Information Form

Mine Number: C/015/019

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: September 4, 1981.

Explanation:

INSPECTION MEMO TO COAL FILE.

\_\_\_\_\_

\_\_\_\_\_

cc:

File in: C/ 015, 019, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

September 15, 1981

Inspection Memo  
to Coal File:

RE: Utah Power & Light Co.  
Wilberg Mine  
ACT/015/018  
Emery County, Utah

DATE: September 4, 1981  
TIME: 8:30 a.m.  
WEATHER: Warm, Fair  
COMPANY OFFICIAL: Larry Guymon  
STATE OFFICIALS: Rex Fidler, Tom Portle, Jean Doutre  
ENFORCEMENT ACTION: NOV #81-7-1-2

Compliance With Permanent Performance Standards

UMC 771 Permits

The applicable permits were available at the minesite for inspection. The U. S. Department of the Interior sent a letter on May 17, 1977, permitting the mine under the Code to Federal Regulations program GS-211. Tentative approval had been granted by DOGM on October 5, 1977. On December 28, 1977, conditional final approval was granted.

UMC 817.11 Signs and Markers

The mine entrance had a sign which was visible and all pertinent information on the sign. Perimeter markers were also observed throughout the minesite.

UMC 817.21-.25 Topsoil

No new developments have required topsoil removal.

UMC 817.41-.52 Hydrologic Balance

A hydrologic monitoring plan was approved on October 19, 1979, in a letter dated November 14, 1979. NPDES permit #UT-0022896 for coal mine water discharge was available at the site. Water monitoring data from standard laboratories provided information on various monitoring points for the months of May, June and July.

UMC 817.45 Hydrologic Balance: Sediment Control Measures

The erosion of the dc was mentioned in the July lower parking lot, the fc 2, group 81-7-1-2 which v

File in:  
 Confidential  
 Shelf  
 Expandable  
Refer to Record No 0006 Date \_\_\_\_\_  
In C/ 015, 019 Internal  
For additional information

he silo pad which  
Wilberg Mine  
Violation No. 2 of

September 15, 1981

Inspection Memo  
to Coal File:

RE: Utah Power & Light Co.  
Wilberg Mine  
ACT/015/018  
Emery County, Utah

DATE: September 4, 1981  
TIME: 8:30 a.m.  
WEATHER: Warm, Fair  
COMPANY OFFICIAL: Larry Guymon  
STATE OFFICIALS: Rex Fidler, Tom Portle, Jean Doutre  
ENFORCEMENT ACTION: NOV #81-7-1-2

Compliance With Permanent Performance Standards

UMC 771 Permits

The applicable permits were available at the minesite for inspection. The U. S. Department of the Interior sent a letter on May 17, 1977, permitting the mine under the Code to Federal Regulations program GS-211. Tentative approval had been granted by DOGM on October 5, 1977. On December 28, 1977, conditional final approval was granted.

UMC 817.11 Signs and Markers

The mine entrance had a sign which was visible and all pertinent information on the sign. Perimeter markers were also observed throughout the minesite.

UMC 817.21-.25 Topsoil

No new developments have required topsoil removal.

UMC 817.41-.52 Hydrologic Balance

A hydrologic monitoring plan was approved on October 19, 1979, in a letter dated November 14, 1979. NPDES permit #UT-0022896 for coal mine water discharge was available at the site. Water monitoring data from standard laboratories provided information on various monitoring points for the months of May, June and July.

UMC 817.45 Hydrologic Balance: Sediment Control Measures

The erosion of the downslope between the surge pad and the silo pad which was mentioned in the July 1 memo had been corrected. At the Wilberg Mine lower parking lot, the following violations were observed. Violation No. 2 of 2, group 81-7-1-2 which was written:

Nature of Violation:

Failure to maintain sediment control measures as designed.

Provision of the Regulations, Act or Permit Violated:

UMC 817.45.

Portion of Operation to Which Notice Applies:

1. From the area of the coal storage silo along the southern drainage channel to the sediment pond.
2. From lower parking lot elevator entrance south along drainage channel to the road culvert.

Remedial Action Required:

1. Clean out trash from the area of coal storage silo to the sediment pond.
2. Clean and redefine drainage channel from lower parking lot elevator entrance to road culvert.

Time for Abatement:

Thirty (30) days, no later than 8:00 a.m., October 4, 1981.

UMC 817.71-.73- Disposal of Underground Development Waste and Excess Spoil and Nonacid, Nontoxic Forming Coal Process Waste

There is not an underground waste disposal site on the surface. However, plans have been submitted to the Division for approval of a site southeast of the permit area and east of the paved road. The review of this by the Division is nearly complete.

UMC 817.89 Disposal of Noncoal Waste

During the inspection, inspectors observed many oil spills and improper storage of flammables throughout the permit area. Because of this, Violation No. 2 of 2 of group 81-7-1-2 was written:

Nature of the Violation: (Refer to July 1, 1981, memo which discusses this problem.)

Noncoal waste including, but not limited to, grease, lubricants, paints, flammable liquids, garbage, abandoned mining machinery generated during underground coal mining activities, shall be placed and stored in a controlled manner in a designated portion of the permit area.

Provision of the Regulations, Act or Permit Violated:

UMC 817.89.

Portion of Operation to Which Notice Applies:

Wilberg Mine permit area.

Remedial Action:

- A. Clean up all oil spills throughout the permit area.
- B. Control flammable materials in noncoal waste disposal area to prevent spillage.

Time for Abatement:

Forty-five (45) days, no later than 8:00 a.m., October 19, 1981.

UMC 817.111-.114 Revegetation

Revegetation of the road and adjacent area north of the lower parking area will occur this fall.

UMC 817.121-.126 Subsidence

Subsidence is surveyed twice a year. Also, the Forest Service in conjunction with UP&L proposes the use of photogrammetry to determine the subsidence in the area. There is no indication of significant subsidence presently observed in the area of the mining operations.

*Rex Fidler*  
REX FIDLER  
RECLAMATION OFFICER

cc: Tom Ehmett, OSM  
Inspection Staff  
Larry Guymon, Emery Mining Corp.

RF/btm

Statistics:

See Price River Coal Company memo dated September 3, 1981  
Grant: A & E