

### Document Information Form

Mine Number: C/015/019

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: JULY 7, 1982

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in: C/015, 019, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

July 7, 1982

Inspection Memo  
to Coal File

RE: Utah Power & Light Company  
Wilberg Mine  
ACT/015/018-B  
Emery County, Utah

Division inspector David Lof conducted a partial inspection of the above mentioned site on May 19, 1982. He was accompanied on the inspection by Larry Guymon of Emery Mining Company.

The installation of the slotted drain across the access road to the portals, as required in NOV N81-4-7-2, #1 of 2, had been completed.

The designed drainage controls for disturbed and undisturbed area runoff on the lower parking pad had been reestablished and a berm installed along the perimeter of the parking pad as requested during the May 5, 1982 inspection (refer to June 29, 1982 memo). The grading of the surge pad, as requested during the May 5, 1982 inspection, in order to eliminate the ponding and erosion problem at the southeast corner of the surge pad, had not been completed. The gully on the downslope from the surge pad to the pad below had been significantly enlarged. It now measured approximately two to three feet wide by two feet deep. Because of this, NAOC 82-4-2-1 was issued. The compliance action required the immediate implementation of a temporary berm along the east side of the silo pad, to prevent runoff from flowing across the fill slope below, and a temporary diversion to the designed drainage ditch. Furthermore, the operator was given until May 24, 1982 to reestablish the silo pad grade to ensure that runoff was properly conveyed to the designed drainage ditch.

The drilling activities which had been conducted on the slope south and east of the coal silo had been completed. According to the operator, the slope where the drilling pad was located was to be recontoured within the next week and the area revegetated this fall.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0023 Date \_\_\_\_\_

In C/ 015, 019, Internal

For additional information

UTAH POWER & LIGHT COMPANY  
July 7, 1982  
ACT/015/018-B  
Page Two

At this time, the Division is still awaiting resubmittal of plans detailing reclamation of the old fan access road. The operator ensured the inspector that said plans would be resubmitted by May 28, 1982.

  
DAVID LOF  
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM  
Larry Guymon, Emery Mining Company  
Inspection Staff

Statistics:

See Skyline Mine memo dated July 7, 1982