

May 3, 1983

Inspection Memo
to Coal File:

RE: Utah Power & Light Company
Wilberg Mine
ACT/015/018-B
Folder No. 7
Emery County, Utah

A partial inspection of the above mentioned minesite was conducted on April 25, 1983 by DOGM Field Specialist Ken Wyatt. Larry Guymon and Dave Northrup accompanied this inspector during the field tour. The purpose of this inspection was to familiarize this inspector with the mine area.

At the time of this inspection the South Wilberg portals were being constructed. The slot drain collecting disturbed area runoff adjacent to the mine water discharge area had been covered over by a steel plate to protect this drain from heavy construction equipment present during portal development.

The undisturbed drainage above the mine water discharge point was flowing, the other undisturbed drainage adjacent to the lower parking area was flowing at a slow rate. The inlets to these bypass culverts were unobstructed. All drainages throughout the mine area appeared functional and adequately maintained at the time of this inspection.

Mr. Guymon indicated that a U. S. Forest Service Special Use permit had been requested for the areas south of the truck loading area. This Special Use permit area includes the sediment ponds and the main access road entering the mine area. No decision has been made to date by the USFS on this request. No compliance problems were observed at this time.

KEN WYATT *KW*
FIELD SPECIALIST

KW/lm

cc: Tom Elmett, OSM
Larry Guymon, Emery Mining Corp.
Joe Helfrich, DOGM

Statistics:

See Valley Camp's Belina #1 Mine memo dated May 3, 1983.
Grant: A & E