

March 15, 1984

Inspection Memo  
to Coal File:

RE: Utah Power and Light Company  
Wilberg Mine  
ACT/015/019, Folder #7  
Emery County, Utah

On January 26, 1984 a partial inspection of the Wilberg Mine was conducted by Ken Wyatt of the Division. Dick Northrup and Val Payne of Emery Mining Corporation accompanied this inspector. The weather was clear and cold approximately 30°.

At the time of this inspection at the Cottonwood portal facilities, sediment pond No. 3 was almost to capacity and should be watched by Emery Mining Corporation personnel in order to sample during any discharge periods. In a letter from UP&L dated February 17, 1984 the surface water monitoring program at Cottonwood Creek was being canceled due to the fact that adequate baseline data has already been accumulated. UP&L is expected to monitor any discharges from the ponds at the Cottonwood portal facilities and the creek as described in the above letter.

The salt storage methods at the Wilberg Mine have changed. Salt was previously being stored adjacent to a disturbed area ditch. This salt pile has been moved to the center of the pad away from any disturbed area drainage ditches. This should reduce further salt influxes into the sediment ponds. No compliance problems were encountered at this time.

Ken Wyatt *KW*  
Field Specialist

KW:re

cc: Tom Ehmett, OSm  
Larry Guymon, Emery Mining Corporation  
Joe Helfrich, DOGM  
Mary Boucek, DOGM

Statistics: See Co-op Mining Company's Bear Creek Canyon Mine memo dated  
March 15, 1984  
79150