



04 30028

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

get

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: February 12, 1987
@ 10:00 p.m.

Permittee and/or Operators Name: Utah Power & Light / Mining Division
Business Address: P.O. Box 310 Huntington, Utah 84528
Mine Name: Wilberg/Cottonwood Permit Number: ACT/015/019
Type of Mining Activity: Underground Yes Surface Other
County: Emery
Company Official (s): Val Payne
State Official(s): Phil Ralphs
Partial: Yes Complete: No Date of Last Inspection: 01/15/87
Weather Conditions: Snowing
Acreage: Permitted 11508 Disturbed 42.5 Regraded Seeded Bonded 42.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 02/12/87

(Comments are Numbered to Correspond with Topics Listed Above)

4.b) Diversions:

Runoff is being routed through diversion ditches to the sediment pond as designed. The berm along the road between the upper parking lot and the materials yard, which separates undisturbed runoff from disturbed runoff, has been "beefed-up" since my last inspection and is functioning properly.

4.c) Sediment Ponds:

The water level in the southern most sediment pond was above the decant level and was discharging. Mr. Payne took monthly discharge samples on February 3, as per their NPDES Permit. Therefore, I did not take any discharge samples. Samples results will be checked during the next Complete Inspection.

Copy of this Report:

Mailed to: Donna Griffin (OSM) & Val Payne (UP&L)
Given to: Joe Helfrich & John Whitehead

Inspector's Signature and Number: Philip M. Repko, #10 Date: 02/23/87