

**Document Information Form**

Mine Number: C/015/019

File Name: Incoming

To: DOGM

From:

Person N/A

Company OFFICE OF SURFACE MINING

Date Sent: APRIL 18, 1989

Explanation:

Ten-DAY NOTICE.

cc:

File in: C/015, 019, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

UNITED STATES DEPARTMENT OF THE INTERIOR Office of Surface Mining Reclamation and Enforcement <b>TEN-DAY NOTICE</b>	Originating Office: <u>Albuquerque Field Office</u>
	<u>625 Silver SW Suite 310</u>
	<u>Albuquerque, New Mexico 87102</u>
	Telephone Number: <u>505-766-1486</u>

Number: X-89-02-107-1 TV 2

Ten-Day Notice to the State of Utah, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal oversight inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: <u>Utah Power &amp; Light</u> <small>(Or Operator if No Permit)</small>	County: <u>Emery</u>	<input type="checkbox"/> Surface
Mailing Address: <u>P.O. Box 310, Huntington Utah 84528</u>		<input checked="" type="checkbox"/> Underground
Permit Number: <u>015/019</u>	Mine Name: <u>Gettwood/Wilburg</u>	<input type="checkbox"/> Other

① NATURE OF VIOLATION AND LOCATION: Failure to certify sediment ponds after construction. The two sediment ponds at the Gettwood Fuel Portals site.

Section of State Law, Regulation or Permit UMC  
Condition believed to have been violated: 817.46


② NATURE OF VIOLATION AND LOCATION: Failure to obtain a <sup>valid</sup> permit before engaging in or carrying out underground coal mining activities. The 90 inch diameter bypass culvert-downstream from guard shack is

Section of State Law, Regulation or Permit  
Condition believed to have been violated: UMC 771.11

NATURE OF VIOLATION AND LOCATION: outside the permit area - approximately 100 feet of the downstream end of the culvert.

Section of State Law, Regulation or Permit  
Condition believed to have been violated:

Remarks or Recommendations:



DIVISION OF OIL, GAS & MINING

Date of Notice: 3-10  
Cert. Return ✓  
P 201 229 309

File in:  
 Confidential  
 Shelf  
 Expandable  
 Refer to Record No. 0052 Date 4-18-89  
 In C/ 015, 019, Incoming  
 For additional information

Rep.: [Signature]  
ade H. Orell

UNITED STATES DEPARTMENT OF THE INTERIOR Office of Surface Mining Reclamation and Enforcement <b>TEN-DAY NOTICE</b>	Originating Office: <u>Albuquerque Field Office</u>
	<u>625 Silver SW Suite 310</u>
	<u>Albuquerque, New Mexico 87102</u>
	Telephone Number: <u>505-766-1486</u>

Number: X-89-02-107-1 TV 2

Ten-Day Notice to the State of Utah, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal oversight inspection (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: <u>Utah Power &amp; Light</u> <small>(Or Operator if No Permit)</small>	County: <u>Emery</u>	<input type="checkbox"/> Surface
Mailing Address: <u>P.O. Box 310, Huntington Utah 84528</u>		<input checked="" type="checkbox"/> Underground
Permit Number: <u>015/019</u>	Mine Name: <u>Gettwood/Wilburg</u>	<input type="checkbox"/> Other

①

NATURE OF VIOLATION AND LOCATION: Failure to certify sediment ponds after construction. The two sediment ponds at the Gettwood Fuel Portals site.

Section of State Law, Regulation or Permit UMC  
Condition believed to have been violated: 817.46


②

NATURE OF VIOLATION AND LOCATION: Failure to obtain a <sup>valid</sup> permit before engaging in or carrying out underground coal mining activities. The 90 inch diameter bypass culvert-downstream from guard shack is

Section of State Law, Regulation or Permit  
Condition believed to have been violated: UMC 771.11

NATURE OF VIOLATION AND LOCATION: outside the permit area - approximately 100 feet of the downstream end of the culvert.

Section of State Law, Regulation or Permit  
Condition believed to have been violated:



Remarks or Recommendations:

DIVISION OF OIL, GAS & MINING

Date of Notice: 4-10-89  
Cert. Return receipt  
P 201 229 309

Signature of Authorized Rep.: [Signature]  
Print Name and ID: Rade H. Orell #107