

0004



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

get page

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 10, 1991
8:00 p.m. to 3:00 p.m.

Permittee and/or Operators Name: PacifiCorp Electric Operations
Business Address: 210 S Main, Suite 2100, SLC, UT 84140-0021
Mine Name: Trail Mountain Exploration Permit Number: ACT/015/019-90D
Type of Mining Activity: Underground X Surface Other
County: Emery
Company Official (s): None
State Official(s): Ken Wyatt, Tom Munson
Partial: X Complete: Date of Last Inspection: NA
Weather Conditions: Clear and warm
Acreage: 4480 Permitted 4480 Disturbed 5 Regraded 5 Seeded 5 Bonded 5
Enforcement action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/

DATE OF INSPECTION: 10/10/91

(Comments are Numbered to Correspond with Topics Listed Above)

Exploration activities on Trail Mountain in 1990 - 91 include eight coal exploration drill holes permitted as a minor exploration activity. These include holes TMTN-1 through TMTN-8.

TMTN-1 was still being worked. The operator onsite indicated that this hole was a problem in that at about 1300 feet they kept hitting sand, water and clay. They were considering abandoning this hole.

11. CONTEMPORANEOUS RECLAMATION

The pads and roads associated with holes TMTN-2, TMTN-3, TMTN-4, TMTN-5 and TMTN-6 had all been recontoured and seeded last year. The topography was acceptable and growth was observed on the pad surface. Holes TMTN-7 and TMTN-8 were reclaimed this year. Seed was observed on the surface.

12. BACKFILLING AND GRADING

All holes except TMTN-1 were backfilled and regraded. They blended in with the surrounding topography.

13. REVEGETATION

Holes TMTN-2 through 6 were revegetated last year. Vegetation looked good, with a variety of grasses and shrubs.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Blake Webster & Guy Davis (PEO)

Given to: Joe Helfrich (DOGM)

Inspectors Signature: Ken Wyatt

#42

Date: 10/28/91