



Norman H. Bangerter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

July 19, 1991

TO: Pam Grubaugh-Littig, Permit Supervisor  
FROM: William J. Malencik *WJM*  
RE: Cottonwood/Wilberg, ACT/015/019, Maps.

The surface facilities map revised May 21, 1991, hydrology undisturbed map revised May 23, 1991, and hydrology disturbed map revised were field checked on July 18, 1991. The undersigned was accompanied by Guy Davis and also an Energy West representative.

The maps have been updated and reflect conditions on the ground. The exception concerns two projects now in the final stage of construction (items 1 and 2 below).

Detail changes that need to be made include the following:

Surface Facilities Map

1. Lower Sediment Trap Under Construction
  - a. Resite the location
  - b. Eliminate non-existent manhole cover adjacent to sediment trap
2. Road Below Former Guard Station
  - a. Show recent constructed curb
  - b. Show gravel filter basin where curb terminates
3. ASCA Area #4
  - a. 18" culvert does not carry same culvert identification. Suggest the culvert be noted on the map as CD-17.

Hydrology

Duplicate the following items noted above on the disturbed hydrology map: 1a, 1b, 2b, 3a, and also add culvert CD-17 identification and design criteria to the map tabulation.

The permittee advised me he would make the required changes promptly and submit them to you without any prompting. Based on the magnitude of changes, I believe when the new maps are received only a map check will have to be made.