

0011



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

August 1, 1991

Mr. Blake Webster
PacifiCorp Electric Operations
Fuel Resources
One Utah Center
210 South Main; Suite 2100
Salt Lake City, Utah 84140-0021

Dear Mr. Webster:

Re: Updated Surface Facilities Map, PacifiCorp Electric Operations,
Cottonwood/Wilberg Mine, ACT/015/019, Folder #2, Emery County, Utah

Enclosed please find a memo documenting changes that need to be made on the surface facilities map.

Please submit these maps by August 20, 1991.

Sincerely,

A handwritten signature in cursive script, reading 'Pamela Grubbaugh-Littig'.

Pamela Grubbaugh-Littig
Permit Supervisor

jbe
Enclosure
AT015019.7



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

July 19, 1991

TO: Pam Grubaugh-Littig, Permit Supervisor
FROM: William J. Malencik *WJM*
RE: Cottonwood/Wilberg, ACT/015/019, Maps.

The surface facilities map revised May 21, 1991, hydrology undisturbed map revised May 23, 1991, and hydrology disturbed map revised were field checked on July 18, 1991. The undersigned was accompanied by Guy Davis and also an Energy West representative.

The maps have been updated and reflect conditions on the ground. The exception concerns two projects now in the final stage of construction (items 1 and 2 below).

Detail changes that need to be made include the following:

Surface Facilities Map

1. Lower Sediment Trap Under Construction
 - a. Resite the location
 - b. Eliminate non-existent manhole cover adjacent to sediment trap
2. Road Below Former Guard Station
 - a. Show recent constructed curb
 - b. Show gravel filter basin where curb terminates
3. ASCA Area #4
 - a. 18" culvert does not carry same culvert identification.
Suggest the culvert be noted on the map as CD-17.

Hydrology

Duplicate the following items noted above on the disturbed hydrology map: 1a, 1b, 2b, 3a, and also add culvert CD-17 identification and design criteria to the map tabulation.

The permittee advised me he would make the required changes promptly and submit them to you without any prompting. Based on the magnitude of changes, I believe when the new maps are received only a map check will have to be made.