



OGMCOAL DNR <ogmcoal@utah.gov>

Cottonwood Mine TMA 001- Update on broken discharge pipe

Lisa Reinhart <lreinhart@utah.gov>

Mon, Jan 5, 2015 at 12:01 PM

To: Keenan Storrar <kstorrar@utah.gov>, Suzanne Steab <suzannesteab@utah.gov>, OGMCOAL DNR <ogmcoal@utah.gov>

Keenan,

I just talked to Dennis Oakley on the phone and am forwarding a summary of the situation with the Trail Mountain Access Discharge Point 001 (TMA001) for the Cottonwood Mine. Last month when they were closing the portal and breaking up the concrete the discharge line was inadvertently broken. Monday December 29th, the contractor was back at the location and repaired the broken line at it should now be functioning properly. Dennis stated it was buried deep enough to prevent freezing. I will inspect it this month to verify it's repair.

Lisa Reinhart
Environmental Scientist
Utah Coal Program
Division of Oil, Gas, and Mining
(801) 538-5437, (801) 359-3940 (Fax)

Web site: <http://ogm.utah.gov>