



# State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Inspection Report

Permit Number:	C0150019
Inspection Type:	PARTIAL
Inspection Date:	Thursday, August 30, 2018
Start Date/Time:	8/30/2018 1:00:00 PM
End Date/Time:	8/30/2018 2:00:00 PM
Last Inspection:	

Representatives Present During the Inspection:
OGM Keenan Storrar

Inspector: Keenan Storrar

Weather: Sunny

InspectionID Report Number: 6237

Accepted by: DHADDOCK  
10/5/2018

Permitee: **PACIFICORP**  
 Operator: **INTERWEST MINING CO**  
 Site: **COTTONWOOD/ WILBERG**  
 Address: **PO BOX 310, HUNTINGTON UT 84528**  
 County: **EMERY**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

### Current Acreages

4,092.00	<b>Total Permitted</b>
27.83	<b>Total Disturbed</b>
21.30	<b>Phase I</b>
21.30	<b>Phase II</b>
21.30	<b>Phase III</b>

### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Division conducted an inspection at the Cottonwood-Wilberg mine on August 30, 2018. Reclamation permit conditions for hillslopes, diversions, and vegetation were inspected. The site remains stable since the last inspection.

Inspector's Signature:

Keenan Storrar,  
Inspector ID Number: 71

Date Wednesday, September 12, 2018



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**4.a Hydrologic Balance: Diversions**

The reclaimed channel was walked up to the junction of the left and right forks of Grimes wash. The channel appears to be functioning as designed.

**4.c Hydrologic Balance: Other Sediment Control Measures**

No erosional features such as rilling or gulying were observed on any of the reclaimed hillslopes. The pocks have retained their structural integrity and appear to be functioning as designed. There has been very little rainfall this year, however it is obvious that no sediment has left the hillslopes and migrated to the channel or offsite.

**13. Revegetation**

There has been very little rainfall since the seed was applied to the reclaimed hillslopes. Vegetation is sparse but it is beginning to be established in the bottom of the pocks. It is anticipated winter moisture will help vegetation become established across the site.

<b>ATTACHMENT A – Photos August 30, 2018 site visit</b>	
	
<p><b>PHOTO 1</b> Reclaimed channel looking up canyon. August 30, 2018</p>	<p><b>PHOTO 2</b> Vegetative growth in bottom of pock. August 30, 2018</p>
	
<p><b>PHOTO 3</b> Vegetative growth in bottom of pock. August 30, 2018</p>	<p><b>PHOTO 4</b> Vegetative growth in bottom of pock. August 30, 2018</p>