



STATE OF UTAH
NATURAL RESOURCES & ENERGY
Oil, Gas & Mining

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

0002

January 18, 1983

Mr. Gary Moreau
District Conservationist
Soil Conservation Service
350 North 400 East
Price, Utah 84501

#13

RE: Soil Survey
Co-op Mining Company
Bear Creek Canyon Mine
ACT/015/025
Emery County, Utah

Dear Mr. Moreau:

I have some questions on a soil survey map that was prepared by the Soil Conservation Service and submitted by Co-op Mining Company for the Bear Creek Canyon Mine. The soils map, which I have enclosed, indicates that the Dantino, D2E, soil is found at the 7,600 foot level on a steep side hill. According to the soil description found in the mine plan, the D2E soil in Bear Canyon is located at the 7,100-7,200 foot level.

If it is possible, could you please clarify this discrepancy and verify if this map was prepared by your office.

If you have any questions, please feel free to call me.

Sincerely,

EVERETT HOOPER
RECLAMATION SOILS SPECIALIST

EH/btb

Enclosure