

March 15, 1984

Inspection Memo  
to Coal File:

RE: Co-op Mining Company  
Bear Creek Canyon Mine  
ACT/015/025, Folder #7  
Emery County, Utah

On January 26, 1984, a partial inspection of the Bear Creek Canyon Mine area was conducted by Ken Wyatt, Field Specialist for the Division. Bill Stoddard was contacted at the scale house prior to this inspection. No Co-op Mining personnel accompanied this inspector on the field tour.

The purpose of this inspection was to examine the drainage system on the southwest corner of the coal stockpile pad. This area was a potential problem as noted during the inspection on January 25, 1984. At the time of this inspection the berm along the southwest corner of this pad had been upgraded to insure that the disturbed area drainage did not flow from the disturbed area into the undisturbed drainage ditches. The disturbed area drainage ditch from the crusher pad down to the coal stockpile pad had been upgraded to help route the disturbed area drainage around the southwest corner of the coal stockpile pad as requested. No compliance problems were encountered.

Ken Wyatt *KW*  
Field Specialist

KW:re

cc: Tom Ehmett, OSM  
Wendell Owen, Co-op Mining Company  
Joe Helfrich, DOGM  
Mary Boucek, DOGM

Statistics: See Co-op Mining Company's Bear Creek Canyon Mine memo dated  
March 15, 1984  
79150