

0015



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John Pyle

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: April 20, 1990
11:00 a.m. - 2:00 p.m.

Permittee and/or Operators Name: Co-Op Mining Company
Business Address: P.O. Box 1245 Huntington, Utah 84528
Mine Name: Bear Canyon Permit Number: ACT/015/025
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): None
State Official(s): Bill Malencik
Partial: XX Complete: Date of Last Inspection: March 7, 1990
Weather Conditions: Cloudy/Rained Prior To Inspection
Acreage: Permitted 1060 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: None - CHECK FOLLOW-UP ITEM

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION April 20, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The mine site was damp from a previous days rain. No significant runoff took place as a result of the storm. The upper mountains were dusted with snow.

1. PERMIT:

Bear Canyon permit expires November 1, 1990. The operators submission is due July 13, 1990.

4b. DIVERSIONS:

The operator recently graded all ditches including the haul road ditches. They did a good job without prompting by the Division and all work was in the category of preventative maintenance.

The culvert has been replaced on the middle pad below the beltline magnet.

4c. SEDIMENT PONDS:

Sediment ponds were checked. Both ponds were stable and both contained water.

INSPECTION REPORT

(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION April 20, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

The cleanout material from sediment Pond A has been stored on the road by the coal loadout area. The Division granted permission to utilize the aforementioned material on roads; however, not to store the material. The operator should make plans to (1) utilize the material this spring or (2) find some other means for disposal to a Division approved site.

4d. OTHER SEDIMENT CONTROL:

Silt fences were checked and all were found in good order.

Copy of this Report:

Mailed to: Co-Op Mining Company/ Gerald Hansen; Kim Mangum

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO



Inspectors Signature and Number: William J. Malencik #26 Date: April 20, 1990