

0014

ACT/015/025
#2

MEC Mangum
Engineering
Consultants

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

RECEIVED

FEB 18 1992

DIVISION OF
OIL GAS & MINING

12 February 1992


Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil, Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Ms. Grubaugh-Littig,

**Re: Updated Plate 3-4. Bear Canyon Mine, Co-Op Mining Company,
ACT/015/025, Emery, County, Utah**

During a recent telephone conversation with Bill Malencik, it was noted that the updated copy of Plate 3-4 submitted on January 6, 1992 did not state which coal seam the map refers to. Bill requested that this be placed on the map. Enclosed are 3 copies of Plate 3-4 which have been updated to include this request.

Thank You,



Charles Reynolds, B.S.

Mining Engineer

Enclosure(s)

cc: Kim Mangum
Co-Op Mining Co.