



United States Department of the Interior

OFFICE OF SURFACE MINING
RECLAMATION AND ENFORCEMENT
SUITE 310
625 SILVER AVENUE, S.W.
ALBUQUERQUE, NEW MEXICO 87102

Mine file
Pam
Lowell
Dianna



In Reply Refer To:

April 14, 1992

CERTIFIED RETURN RECEIPT #P 965 799 223

Mr. Lowell P. Braxton, Associate Director, Mining
Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: NOV 92-40-4-1, Co-Op Mining Company, Bear Canyon Mine
Permit ACT/015/025

*Pam do photos 7-87
and 7-87A in the
MAP provide character
of the exceptions with
that enumerated
in the TDR?
LBS*

Dear Mr. Braxton:

The above referenced Notice of Violation (NOV) issued by your office on March 12, 1992 for a violation of R645-301-722 and R645-301-722.200, failing to provide cross sections of diversions, was vacated by you on March 30, 1992. The reason given for vacating the NOV was that hydrology maps found in the permit application as Plates 7-1A through 7-1D contain cross sections that address the requirements of R645-301-722.

The alleged violation was identified during a Random Oversight Inspection conducted on March 12, 1992. At that time action on the violation was deferred to the Division of Oil, Gas and Mining. A thorough review of the above referenced plates did not find the cross sections for diversions. Due to the fact that the previous State enforcement action has been vacated and the violation still exist I am issuing Ten-Day Notice 92-02-352-003 TV1 for a violation of R645-301-722.200.

Sincerely,

Russell Porter
Reclamation Specialist



APR 17 1992

DIVISION OF
OIL GAS & MINING

Enclosure

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office: OFFICE OF SURFACE MINING
625 SILVER AVE., SW, SUITE 310
ALBUQUERQUE, NM 87102
Telephone Number: 505-766-1486

Number: X-92-02-352-003 TV 1

Ten-Day Notice to the State of UTAH DIVISION OF OIL, GAS AND MINING

You are notified that, as a result of A FEDERAL INSPECTION (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: CO-OP MINING
(Or Operator if No Permit)

County: EMERY

Surface

Mailing Address: P.O. BOX 1245, HUNTINGTON, UTAH 84528

Underground

Permit Number: ACT-015-025

Mine Name: BEAR CANYON

Other

NATURE OF VIOLATION AND LOCATION: FAILURE TO PROVIDE CROSS SECTIONS OF DIVERSIONS. ALL DIVERSIONS EXCEPT D-10, D-20 AND D-70

Section of State Law, Regulation or Permit Condition believed to have been violated: R645-301-722.200

NATURE OF VIOLATION AND LOCATION: _____

Section of State Law, Regulation or Permit Condition believed to have been violated: _____

NATURE OF VIOLATION AND LOCATION: _____

Section of State Law, Regulation or Permit Condition believed to have been violated: _____

Remarks or Recommendations: _____

Date of Notice: 4-14-92

Signature of Authorized Rep.: Russ Porter

cont. receipt # P965799223

Print Name and ID: RUSS PORTER 352