

Copy Hugh

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

9 July 1992

Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED

JUL 13 1992

**DIVISION OF
OIL GAS & MINING**

Dear Pamela:

Re: Submittal Made 8 May 1992, Relocation of Disturbed Area Boundaries for D-8U, Plate 7-5 Rev Table, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025, Emery County, Utah #2

At my request you arranged for a meeting between Hugh Klein of the Division and myself on 1 July 1992. During the meeting Mr. Klein explained to me that he had not reviewed all of the issues submitted 8 May 1992 but he did have two concerns.

The first issue mentioned was the revision note on Plate 7-5. Mr Klein requested that a separate revision note be made for the extension of the boundaries at C-12U. This can easily be completed. I request that you require this on the final copies.

The second issue related to the boundary change near Sediment Pond A. When the new maps were submitted in 1991, the disturbed boundary did not include the area where ditch D-8U is found. We became aware of this situation shortly before making the 8 May 1992 submittal. An on-site survey was made and the maps were corrected to accurately show the originally disturbed area and length of D-8U. Reclamation areas and bonding were modified for the submittal to indicate this correction.

A meeting was scheduled for 16 July 1992 yesterday and I am sure we can close any open issues at that time.

Thank you,

Kimmy C. Mangum

Kimmy C. Mangum, P.E.
Permitting & Compliance Consultant.

attachment(s)

cc: Co-Op Mining Co.