



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 10/4/96 / 8:00a.m.-12:00p.m.
Date of Last Inspection: 9/16/96

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025
Permittee and/or Operator's Name: Co-Op Mining Company
Business Address: P. O. Box 1245, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Charles Reynolds, Environmental Coordinator
State Officials(s): Peter Hess Federal Official(s): None
Weather Conditions: Clear, Cool, 60's
Existing Acreage: Permitted- 1531 Disturbed- 24 Regraded- 0 Seeded- 0 Bonded- 24
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 list various permit conditions and their evaluation status.



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 10/4/96

(Comments are Numbered to Correspond with Topics Listed Above)

4a. HYDROLOGIC BALANCE: DIVERSIONS

The permittee has completed half of the installation for the concrete water bar diversion across the main canyon access road by pond "B", (subject of amendment 96C).

All diversions, which were inspected, were capable of functioning as designed.

8. NONCOAL WASTE

The Bear Canyon #1 Mine portal pad material storage area was in need of cleanup. Mr. Reynolds assigned an employee to address and correct this problem during the course of the inspection.

13. REVEGETATION

The permittee has reseeded the topsoil pile, which is located on the NW corner of the bath house. Other areas are pending.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Co-Op Mining Company

Marcia Petta (OSM)

Given to: Joe Helfrich (DOGMA)

Filed to: Price Field Office

Date: October 9, 1996

Inspector's Signature: \_\_\_\_\_



#46

Peter Hess