

0009



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 4/22/99 / 12:15p.m.-3:00p.m.
Date of Last Inspection: 3/29/99

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025
Permittee and/or Operator's Name: Co-Op Mining Company
Business Address: P. O. Box 1245, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Charles Reynolds
State Officials(s): Peter Hess Federal Official(s): None
Weather Conditions: Snow flurries in area
Existing Acreage: Permitted- 1032.75 Disturbed- 24 Regraded- 0 Seeded- 0 Bonded- 24
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Lists 21 items related to permit conditions and their evaluation status.

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 4/22/99

(Comments are Numbered to Correspond with Topics Listed Above)

Note: Mr. Reynolds informed me this day that mining has been reinitiated in the Blind Canyon seam of the #1 Mine. Only one CM section remains in operation in the Tank seam.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

The permittee has implemented several new environmental controls in the maintenance shop area:

- 1) a lubricant storage area for new product has been implemented inside the shop.
- 2) the used oil filter crusher has been moved inside the shop.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Charles Reynolds (Co-Op)

Henry Austin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: April 23, 1999

Inspector's Signature: \_\_\_\_\_

Peter Hess  
Peter Hess

#46