



## State of Utah

### Department of Natural Resources

MICHAEL R. STYLER  
*Executive Director*

### Division of Oil, Gas & Mining

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

November 9, 2005

Charles Reynolds, General Manager  
Co-Op Mining Company  
P. O. Box 1245  
Huntington, Utah 84528

Subject: Escarpment Failure, Co-Op Mining Company, Bear Canyon #4 Mine, C/015/0025, Task ID #2343, Outgoing File

Dear Mr. Reynolds:

The above-referenced amendment has been reviewed. There is a deficiency that must be adequately addressed prior to approval. A copy of our findings is enclosed for your information. In order for us to continue to process your application, please respond to these deficiencies by December 9, 2005.

If you have any questions, please call me at (801) 538-5286 or Jim Smith at (801) 5385262.

Sincerely,

D. Wayne Hedberg  
Permit Supervisor

an  
enclosure  
cc: Price Field Office  
O:\015025.BCN\FINAL\WG2343\Def2343.doc

## **TECHNICAL DEFICIENCIES**

### **Escarpment Failure, Task ID #2343**

**R645-301-521.141**, The Permittee must update Plate 3-4a to show the changes to the mine plan and subsidence areas. Specifically, the Permittee must either change the dimensions of the longwall panel scheduled to be mined between December 2009 and February 2010 or state that mining will not occur until approval is granted to subside the entire area.

O:\015025.BCN\FINAL\WG2343\deflist2343.doc