

## OGMCOAL - RE: Castle Valley Mining

---

**From:** Daron Haddock  
**To:** Jaren Jorgensen  
**Date:** 8/3/2011 8:09 AM  
**Subject:** RE: Castle Valley Mining  
**CC:** Karl Houskeeper; OGMCOAL

---

Jaren,

You are hereby granted an extension of time to submit the Bear Canyon subsidence map and mining projections map requested as part of your annual report. Hopefully this additional time will allow you to produce more accurate and meaningful maps. Please call if you have any questions.

Sincerely,

to September 1, 2011 to

Daron R. Haddock  
 Coal Program Manager  
 Utah Division of Oil, Gas & Mining  
 (801) 538-5325

>>> Jaren Jorgensen <JJorgensen@rhinolp.com> 8/3/2011 7:34 AM >>>

If you could possible give me to September 1st that would be good. The reason the length is because of the scheduling of a surveyer to help do the work. As well as we need to set new surface control. We cannot find COP's.

Thanks for your help.

**Jaren Jorgensen**  
**Engineering**

---

### CASTLE VALLEY MINING

**5550 W Bear Canyon RD**  
**Huntington, UT 84528**  
**Box 475**  
**Phone: 435 687 5454**  
**Fax: 435 687 5037**  
**E-mail : [jjorgensen@rhinolp.com](mailto:jjorgensen@rhinolp.com)**

---

**From:** Daron Haddock [daronhaddock@utah.gov]  
**Sent:** Tuesday, August 02, 2011 5:36 PM  
**To:** Jaren Jorgensen  
**Subject:** Re: Castle Valley Mining

That will be okay. How much more time to do you need? A couple of weeks?

Daron R. Haddock  
 Coal Program Manager  
 Utah Division of Oil, Gas & Mining  
 (801) 538-5325

>>> Jaren Jorgensen <JJorgensen@rhinolp.com> 8/2/2011 2:46 PM >>>

Darron,

I was looking at my mail and realized that I needed to have turned in my subsidence map and projections map. I do have these to turn in but I was hoping to get a little more time because I am in the middle of a full check survey out of the mine. We believe that the underground does not match the surface. So we are doing a traverse from underground to the surface to link the two.

Could I get a little more time to complete this survey and get those maps to you more accurate?

I hope that we can work something out.

Thanks,

**Jaren Jorgensen**  
**Engineering**

---

### **CASTLE VALLEY MINING**

**5550 W Bear Canyon RD**

**Huntington, UT 84528**

**Box 475**

**Phone: 435 687 5454**

**Fax: 435 687 5037**

**E-mail : [jjorgensen@rhinolp.com](mailto:jjorgensen@rhinolp.com)**