



Citation for Non-Compliance
Utah Coal Regulatory Program
 1594 West North Temple, Salt Lake City, UT 84114
 Phone: (801) 538-5340 Fax: (801) 359-3940

Citation #: 19151
Permit Number: C0150025
Date Issued: 06/18/2015

NOTICE OF VIOLATION **CESSATION ORDER (CO)** **FAILURE TO ABATE CO**

Permittee Name: CASTLE VALLEY MINING LLC	Inspector Number and ID: 1 JHELFRIC
Mine Name: BEAR CANYON MINE	Date and Time of Inspection: 05/13/2015
Certified Return Receipt Number: 7012346000295596472	Date and Time of Service: 06/18/2015

Nature of condition, practice, or violation:
 The permittee has not maintained the inlets to sediment ponds A, B, C, and D in accordance with Appendix 7F of the approved mining and reclamation plan (MRP).

Provisions of Act, regulations, or permit violated:
 R645-301-742.123

This order requires Cessation of ALL mining activities. (Check box if appropriate.)

<input type="checkbox"/> Condition, practice, or violation is creating an imminent danger to health or safety of the public.	<input type="checkbox"/> Permittee is/has been conducting mining activities without a Permit.
<input type="checkbox"/> Condition, practice, or violation is causing or can reasonably be expected to cause significant, imminent environmental harm to land, air, or water resources.	<input type="checkbox"/> Permittee has failed to abate Violation(s) included in <input type="checkbox"/> Notice of Violation or <input type="checkbox"/> Cessation Order within time for abatement originally fixed or subsequently extended.

This order requires Cessation of PORTION(S) of mining activities.

Mining activities to be ceased immediately: Yes No **Abatement Times (if applicable).**

	30 days, no later than 5:00 Pm Friday
	July 17th for the submittal of plans for
	ponds B & D and repair of inlets for ponds
	A & C.

Action(s) required: Yes No

Sediment Pond A: Clean and reestablish the rip-rapped inlet channel the has been eroded and place the waste material on the appropriate coal stockpile pad.

Sediment Pond B: Refer to # 4b of the attached DOGM inspection report.

Sediment pond C: Clean and reestablish the rip-rapped inlet channel the has been eroded. Repair the erosion on the outslope of the leachfield upstream of pond C.

Sediment Pond D: Refer to # 4b of the attached DOGM inspection report.

Jaren Jorgensen (Print) Permittee Representative	JOE HELFRICH (Print) DOGM Representative
<i>Jaren Jorgensen</i> Permittee Representative's Signature - Date	<i>Joe Helfrich</i> DOGM Representative's Signature - Date

SEE REVERSE SIDE Of This Form For Instructions And Additional Information