



ACT/OIS/ Mine file  
# 2 S. Linnay

Norman H. Bangerter  
Governor

Suzanne Dandoy, M.D., M.P.H.  
Executive Director

ACT/OIS/032

December 10, 1986  
801-538-6170

RECEIVED  
DEC 16 1986

DIVISION OF  
OIL, GAS & MINING

Mr. Lowell Braxton, Administrator  
Mineral Resource Development &  
Reclamation Program  
State of Utah, Natural Resources  
Oil, Gas & Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180

Dear Mr. Braxton:

We have reviewed the Tract 1 Mid Permit Term Review, Stipulation Response, Genwal Coal Company, Crandall Canyon Mine, ACT/OIS/032, Folder no. 2, Emery County, Utah.

Our only comment is to reiterate what was stated in a letter to the Genwal Coal Company on September 5, 1985. Before the sludge is transported to the Sinbad landfill site, it must be stabilized to remove water by mechanical means or by allowing it to air dry until it contains no free moisture. The sludge should be of a consistency that will allow it to maintain its shape when unconfined. The Sinbad Construction landfill site was not designed or approved to receive wastes containing free liquids.

If you have any questions, please contact Mary Pat Bock of my staff.

Sincerely,

Brent C. Bradford, Director  
Bureau of Solid & Hazardous Waste

MPB/k11  
8464U/25

c: Genwal Coal Company  
Sinbad Construction - Emery County  
Gerald Story, Southeastern District Health Department