

GENWAL COAL COMPANY

P.O. Box 1201 • Huntington, Utah 84528
 Telephone (801) 687-9813

Mine File
 W. Hedberg
 S. Linnell

RECEIVED
 JAN 23 1987

January 21, 1987

DIVISION OF
 OIL, GAS & MINING

Mr. Lowell Braxton
 Department of Natural Resources
 Division of Oil, Gas and Mining
 355 W. North Temple
 3 Triad Center
 Suite 350
 Salt Lake City, UT 84180-1203

Re: Incidental Boundary Change (IBC), response to letter dated
 January 6, 1987. ACT/015/032.

Dear Mr. Braxton,


As you requested in your letter dated January 6, 1987 please
 find enclosed for your review and inclusion in the Genwal Coal
 Company Permits Tract 1 and 2 two maps delineating the emergency
 IBC change. 10 copies
 each

Plate 3-2 needs to be inserted in the Tract 1 permit and the
 map labeled Plate 3-1 is to be inserted in the Tract 2 permit.
 These maps replace the existing Plates 3-2 and 3-1 in the
 appropriate MRPs.

I would also like to note a change in the proposed mine
 development for your approval, this change is the single entry
 driven from 1st west panel to the 2nd west panel. This entry is
 utilized for moving equipment from one section to next section in
 an area of adequate height. I have talked with Mr. Steve Falk of
 the BLM and he has verbally approved the change. I will send him
 a map of area for his approval. X

If you should have any further questions or comments please
 feel free to contact me at 637-7383. Thank you for your time and
 consideration.

Sincerely yours,


 Andrew C. King

enc.