

0000



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

Jeh

scd

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 25, 1987
2:10 pm to 4:40 pm

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P. O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Wayne Douglas
State Official(s): Rick Summers & Dave Lof
Partial: Complete: Date of Last Inspection: 2/18/87
Weather Conditions: Clear, patchy snow cover
Acreage: Permitted 164.4 Disturbed 5.15 Regraded 0.5 Seeded 0.5 Bonded 5.15
Enforcement Action: none.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	(X)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION 3/25/87

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits The inspection report for the last complete inspection (dated 12/18/86) indicated that documentation for liability insurance renewal was not available at the mine office. The inspection of the mine office records indicated this situation has been corrected. A copy of the insurance binder with an effective date for the policy of 12/22/86 was available at the office.

4b. Diversions. It was noted during this inspection that the third junction of the white PVC pipe from the portal pad to the mine site access road had become separated due to the weight of ice in the pipe. The pipe was still partially functional and no evidence of a pipe discharge having occurred was observed. Wayne Douglas indicated he would have the pipe fixed by next Tuesday (March 31, 1987).

4e. Surface and Ground Water Monitoring. Monitoring data was available at the mine office as follows: 1) NPDES reports were available through 12/31/86, 2) Data for Crandall Canyon (upstream and downstream stations) were available for 3/30/87, 3) Data for SP-19, 22, 36, and 58 were available through 11/20/86 4) field sheets indicated that the springs were inaccessible for the last quarter sampling.

Copy of this Report:

Mailed to: Donna Griffin - OSM Charles Gent - Genwal Coal Co.

Given to: Joe Helfrich and Susan Linner - DOGM

Inspectors Signature and Number: 15 Date: 4/24/87