

January 4, 1988

TO: File

FROM: Randy Harden, Reclamation Engineer 

RE: Proposed On-Site Loadout Facility, Crandall Canyon Mine, Genwal Coal Company, ACT/015/032, Emery County, Utah

Summary:

The operator has sent revised plates to the Division in its request to include a loadout facility as part of the permit area operations. The operator has also included letters of this request to the Department of Air Quality and the United States Forest Service.

The information submitted by the operator is not considered to be complete. The operator has not provided suitable text and descriptive information of the proposed facilities; has not submitted such information in a manner which can suitably be inserted into the plan; and has not provided plans and designs for the construction, maintenance, and reclamation of the facilities.

Body:

Maps submitted by the operator are generally considered to be adequate for the proposed loadout facility. The operator needs to describe the loadout facility as required in UMC 784.11 through UMC 784.16, UMC 784.24, UMC 784.26 and UMC 800, and incorporate that information into the text of the MRP, in order to consider the proposal complete and in accordance with Subchapter K of the Regulations.

Bonding calculations for the reclamation of the proposed facilities must also be included with the proposal. The addition of the loadout may result in a modification of the bonding requirements for Genwal.

Page 2
ACT/015/032
January 4, 1988

Until such time as the information regarding the description of the loadout facility is provided by Genwal to the Division, this proposal cannot be accepted. Additionally, incorporation of the loadout facility will also be dependent on stipulations or other requirements of the Department of Air Quality and the Forest Service.

jr
cc: J. Leatherwood
S. Linner
1384R/12:13