

Orig: Mine File 015-032 #5
S. Libby, L. Bragg

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

Originating Office:
Albuquerque Field Office
625 Silver SW Suite 310
Albuquerque, New Mexico 87102
Telephone Number: 505-766-1486

Rec. 1006M
3-9-89

TEN-DAY NOTICE 0007

Number: X-89-02-107-1 TV 1

Ten-Day Notice to the State of Utah, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal oversight insp. 3-7-89 (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: <u>Grandval Coal Company</u> <small>(Or Operator if No Permit)</small>	County: <u>Emery</u>	<input type="checkbox"/> Surface
Mailing Address: <u>P.O. Box 1201, Huntington, Utah 84527</u>		<input checked="" type="checkbox"/> Underground
Permit Number: <u>057052</u>	Mine Name: <u>Crandell Canyon</u>	<input type="checkbox"/> Other

NATURE OF VIOLATION AND LOCATION: All surface drainage from the disturbed, including disturbed areas that have been graded, seeded, or planted, shall be passed through a sedimentation pond,

Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: a series of ponds, or a treatment facility before leaving the permit area -

Location: The drainage from the Forest Service Parking lot/snow storage,

Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: The outslope of the road from the truck turnaround to the loading area (approximately 220 feet of outslope) and the three topsoil stockpiles

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817.42

Remarks or Recommendations: Located along USFS/Head Road.

Date of Notice: 3-7-89
Cert. Mail
P201 229 422

Signature of Authorized Rep.: [Signature]
Print Name and ID: Rada H. Orell #107