

Genwal Coal Co., Inc.

P.O. Box 1201 • Huntington, Utah 84528-1201 • (801) 687-9813

August 30, 1989

Susan c. Linner
State of Utah
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED
SEP 05 1989

Div. of Oil, Gas & Mining

Re: Deficiency, amendment on proposed road burm at the Genwal Coal Co.,
Crandall Canyon Mine, ACT/015/032.

Dear Ms. Linner:

In response to your June 21, 1989 correspondence relating deficiencies in the proposed road burm submittal of May 9, 1989, I would formally submit the following information for commitment and clarification .

To insure that blading and movement of road gravel from the road surface at the truck turnaround area does not migrate to the road outslope, Genwal Coal Co. proposes to pave along the truck turnaround area in question with approximately 4 inches of asphalt. The road section in question would be graded to slope away from the outslope to direct and channel runoff to the existing drainage system. At the outslope shoulder of the road, it would be proposed to thicken and extenuate the asphalt to form a drainage barrier to direct runoff away from the outslope area.

It is also proposed to do additional contemporaneous revegetation along the road outslope this planting season.

Should you have any questions or need additional information please contact me at 687-9813.

Sincerely,




Allen Childs

ac

Attachment

cc: H. Sandbeck

R. Summers



PROPOSED PAVED ROADWAY

RECEIVED
SEP 05 1989

DIVISION OF
OIL, GAS & MINING

PLATE 3-1