

0001  
1-10-89 7050



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*John SA*

Norman H. Bangertter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: January 4, 1989  
11 a.m. to 4 p.m.

Permittee and/or Operators Name: Genwal Coal Company  
Business Address: P.O. Box 1201, Huntington, Utah 84527  
Mine Name: Crandall Canyon Permit Number: ACT/015/032  
Type of Mining Activity: Underground XX Surface      Other       
County: Emery  
Company Official (s): Andy King and Lannie Burnside  
State Official(s): Harold G. Sandbeck  
Partial:      Complete: XXX Date of Last Inspection: December 13, 1989  
Weather Conditions: Overcast and cold  
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75  
Enforcement Action:     

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	( )	( )	(XX)
2. SIGNS AND MARKERS	(XX)	( )	( )	( )
3. TOPSOIL	(XX)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(XX)	( )	( )	(XX)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	( )	( )	(XX)
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	(XX)	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION January 4, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. On this partial inspection, both the Genwal and Mohrland sites were inspected.

1. Permits.

Mohrland Site

On December 6, 1988, the Division informed Genwal Coal Company that the amendment issued for the Mohrland Temporary Screening and Crushing Facility will expire on December 28, 1988 and all screening and crushing must stop as of that date. Genwal will then have 30 days to remove the processing equipment and all signs and markers.

During the inspection, it was noted that the processing equipment was being dismantled. The operator was informed to inspect and dress up (if necessary) ditches, berms and any other hydrologic structures before vacating the site.

Condition #4 required the operator to provide documentation from Utah Railway that they wish the spillway structure to remain or else the spillway structure must be removed. On January 9, 1989, Utah Railway Company requested by letter that the spillway structure be left in place.

4. Hydrologic Balance:

b. Diversions.

Genwal Site

The operator was informed to continue maintaining ditches and berms as needed.

d. Other Sediment Control Measures.

Genwal Site

During winter months, the Forest Service Parking Lot is used to store snow. Straw bales had been installed south of the Forest Service Parking Lot. These straw bales are to remain in place throughout the winter and spring months. The straw bale treatment can be removed after all the stored snow has melted. For additional information, the reader is referred to the June 13, 1988 inspection report.

INSPECTION REPORT  
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION January 4, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

Evidence of wildlife eating the straw bale treatment facilities was noted throughout the mine site. The operator was informed to maintain these treatment facilities as needed.

Copy of this Report:

Mailed to: Andy King (Genwal Coal), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Hawes, J. A.* #27 Date: 01/10/89