



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 27, 1989
8:00 a.m. to 4:00 p.m.

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground XX Surface Other
County: Emery
Company Official (s): Allen Childs
State Official(s): Harold G. Sandbeck
Partial: Complete: XXX Date of Last Inspection: June 16, 1989
Weather Conditions: Clear and warm
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75
Enforcement Action: N89-27-9-1 (See 3.)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	(XX)
3. TOPSOIL	()	(XX)	()	(XX)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	()
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	(XX)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(XX)	()	()	()
7. COAL PROCESSING WASTE	()	()	(XX)	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	(XX)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(XX)	()	()	(XX)
12. BACKFILLING AND GRADING	(XX)	()	()	()
13. REVEGETATION	(XX)	()	()	()
14. SUBSIDENCE CONTROL	(XX)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(XX)	()
16. ROADS				
a. CONSTRUCTION	(XX)	()	()	()
b. DRAINAGE CONTROLS	(XX)	()	()	()
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(XX)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(XX)	()	()	()

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION July 27, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. On this complete inspection, the undersigned inspector was accompanied by Alan Childs (Operator's Environmental Engineer) and Rade Orel (OSM Oversight Inspector). Ground conditions were relatively dry.

1. Permits.

A permanent program mining permit was issued to Genwal Coal Company on June 14, 1989.

Forest Service Parking Lot Oversight Concern

OSM may have a concern with the United States Forest Service (USFS) Parking Lot. The USFS parking lot may be related to the mining operation. The OSM oversight inspector was advised that the USFS issued a Special Use Permit for this parking lot. Furthermore, the USFS specifically requested that the operator install this parking lot for public use.

Stipulation/Field Amendment Extension

The Division granted a August 7, 1989 extension for the following stipulations and field amendments:

Stipulation USFS - (1)
Stipulation UMC 771.23 - (1) - SCL
Field Amendment 89B Proposed road berm
Field Amendment 89C Sediment pond riser modification

2. Signs and Markers.

The operator was informed that additional buffer zone signs may be required at the upper and lower top soil stockpiles.

3. Topsoil.

N89-27-9-1

N89-27-9-1 was issued on July 27, 1989 for failure to comply with the approved plan. SAE 4 and SAE 7 requires installation of treatment controls as described in the plan on pages 7-72 and 7-72b. The operator must place treatment control measures along the toe of the outslope at SAE 4 by August 14, 1989 and comply with the approved plan or submit a revision. The abatement date for the above mentioned violation is September 8, 1989 at 5:00 p.m.

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION July 27, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

4. Hydrologic Balance:

c. Sediment Ponds and Impoundments.

The 2nd quarter 1989 pond inspection report was checked. Except for the documented small pond leak, no other problems were noted.

11. Contemporaneous Reclamation.

Step Slope Irrigation Log Inspection

The irrigation log was inspected up to the week of July 10, 1989. No problems were found.

Copy of this Report:

Mailed to: Allen Childs (Genwal Coal), Price Office and Brian Smith(OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Harold J. Fann* #27 Date: 8/1/89