



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

September 26, 1989

Mr. Allen Childs
Genwal Coal Company
P.O. Box 1201
Huntington, Utah 84528

Dear Mr. Childs:

Re: Deficiency, Amendment, Small Area Exemptions, Genwal Coal Company, Crandall Canyon Mine, ACT/015/032-89A, Folder #2, Emery County, Utah

The Division has completed review of your company's submittal received September 12, 1989. The plans were reviewed by Rick Summers of the Division's technical staff. The map submitted is inadequate to identify the small area exemptions. The deficiencies as outlined in the attached memo should be resolved with your map submittal required by October 14, 1989.

If you have any questions, please call Rick Summers or me.

Sincerely,

Susan C. Linner
Susan C. Linner
Reclamation Biologist/
Permit Supervisor

cl
Attachment
cc: J. Helfrich
R. Summers
BT45/317



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

September 21, 1989

TO: Susan C. Linner, Permit Supervisor

FROM: Rick P. Summers, Reclamation Hydrologist *RPS*

RE: Small Area Exemptions (received September 12, 1989), MRP Amendment ACT/015/032-89A, Genwal Coal Company, Crandall Canyon Mine, ACT/015/032, Folder #2, Carbon County, Utah

SUMMARY:

The above referenced proposal was submitted in response to a Conditional Approval issued by the Division on August 2, 1989. The information submitted is not adequate for approval.

The material does address the sediment control measures for and identifies the USFS parking area as a small area exemption. However, the map submitted does not include the USFS parking area within the disturbed area boundary. The undisturbed boundary on this map should be extended to include this area and a boundary (as per current legend) added around this area identifying this area as a small area exemption. During the course of this review it became apparent that the maps in the current MRP need updating. The following plates should be revised to include the items requested above and correct disturbed area boundaries (especially along the access road). All plates should have identical boundaries delineated and labeled. These plates are 3-1, 3-4, 3-5, 7-1, 7-5, 7-5a, and 7-5c.

RECOMMENDATION:

Request the above information be submitted prior to final approval.

cc: H. Sandbeck
BT6005/170