

7050



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

DR7
Gek

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 23, 1990
9:00 am to 12:30 pm

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Jim Pruitt
State Official(s): David Darby, Geologist
Partial: Complete: Date of Last Inspection: February 28, 1990
Weather Conditions: Clear, warm
Acreage: Permitted 164.4 Disturbed 5.15 Regraded 0.5 Seeded 0.5 Bonded 5.15
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION March 23, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

Genwall has requested a right-of-way from the Bureau of Land Management which would connect the existing mine with State leases (ML-21568 and M-21569) held by the Nevada Electric Investment Company (NEICO). The proposal is currently being evaluated.


4. Hydrologic Balance: Surface and Ground Water Monitoring

Warm weather conditions had caused snow accumulated on disturbed areas to melt creating muddy conditions around the mine yard. Traffic on the mine yard compounded the situation where mud became several inches deep. I suggested to the operator some methods of routing some of the runoff to keep it from running over the pad. No runoff was leaving the disturbed area, it was eventually routed into the sedimentation pond. The pond contained the runoff with the water level several feet below the outflow.

Copy of this Report:

Mailed to: Allen Childs-Genwal; Brian Smith-OSM; Price Field Office

Given to: David Darby, Joe Helfrich, Daron Haddock

Inspectors Signature and Number:  David W. Darby #18 Date: April 6, 1990