



NO. N 90-17-5-2

notice of violation

To the following Permittee or Operator:

Name Genwal Coal Company

Mine Crandall Canyon Mine Surface Underground Other

County Emery State UT Telephone 687-

Mailing Address PO Box 1201 Huntington Utah 84528

State Permit No. ACT 1015/032

Ownership Category State Federal Fee Mixed

Date of inspection Sept 5, 1990, 19

Time of inspection 8:30 a.m. p.m. to 5:30 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Sept 7, 1990

Time of service/ mailing 3:00 a.m. p.m.

Allen Childs
Permittee/Operator representative

Mine Manager
Title

Signature
Lynn Kunsler
Division of Oil, Gas & Mining representative

Senior Reclamation Biologist
Title

Signature
[Signature]

17
Identification Number

SEE REVERSE SIDE

WHITE-DOGMI YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N90-17-5-2

Violation No. 1 of 2

Nature of violation

Failure to conduct Subsidence Monitoring in accordance to the approved plan

Provisions of act, regulations or permit violated

R614-301-525,140

R614-301-632.

R614-300-142.

Portion of operation to which notice applies

Area above workings

Remedial action required (including any interim steps)

Submit subsidence reports as specified in MRP

Abatement time (including interim steps)

By 5:00 PM ON October 1, 1990



NOTICE OF VIOLATION NO. N 90-17-5-2

Violation No. 2 of 2

Nature of violation

Failure to conduct water monitoring in accordance with approved plan.

Provisions of act, regulations or permit violated

R614-301-731,220
R614-301-731,210
R614-300-142.

Portion of operation to which notice applies

Water monitoring stations
Not all scheduled parameters were measured during
October & December 1989 and July 1990

Remedial action required (including any interim steps)

NONE

Abatement time (including interim steps)

After the fact violation - no abatement possible