

RECEIVED

JUL 25 1991

DIVISION OF  
OIL GAS & MINING**EarthFax**EarthFax  
Engineering Inc.  
Engineers/Scientists  
7324 So. Union Park Ave.  
Suite 100  
Midvale, Utah 84047  
Telephone 801-561-1555

July 24, 1991

Mr. Daron Haddock  
Division of Oil, Gas, and Mining  
State of Utah Natural Resources  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203SUBJECT: Crandall Canyon Mine - permit correction, and rescheduling drilling  
of in-mine groundwater monitoring wells.

Dear Daron:

Enclosed please find 14 revised copies of page 14-27 of the Crandall Canyon Mining and Reclamation Plan. These changes to Chapter 14, State Leases ML-21568 and ML-21569, were made in response to a 7/23/91 telephone communication between Jay Marshall (Genwal) and Sharon Falvey (DOGM). Sharon pointed out that section 14.5.1.5 incorrectly states that mine discharge is routed via the sediment pond prior to discharge into Crandall Creek. Mine discharge water is not routed through the sediment pond.

Genwal has committed to drilling two additional in-mine groundwater monitoring wells in Lease ML-21569 to more accurately delineate the potentiometric surface and effects of mine dewatering on the hydrologic system. Well locations and a schedule for drilling (August) were agreed upon during conversations with Genwal and DOGM (David Darby). However, due to a slower mining rate than anticipated, one of these locations is yet to be mined. Consequently, Genwal has rescheduled drilling of these wells for the fourth quarter of 1991. The affects of mine dewatering on the hydrologic system will be reevaluated and Chapter 14 updated.

If you have any questions or comments please don't hesitate to call myself (561-1555), or Jay Marshall (687-9813).

Sincerely,

Brent K. Bovee  
Geologistcc: David Darby, DOGM  
Jay Marshall, Genwal