

# GENWAL COAL COMPANY

August 6, 1991

RECEIVED

AUG 15 1991

DIVISION OF  
OIL GAS & MINING

Mr. Daron Haddock  
Division of Oil, Gas & Mining  
3 Triad Center, Suite 350  
355 West North Temple  
Salt Lake City, UT 84180-1203

RE: Permit # ACT 015-032  
Genwal Coal Company  
Weekly Subsidence Inspection Report

Dear Mr. Haddock:


This letter is to inform you that Genwal Coal Company's Crandall Canyon Mine initiated its second mining (pillaring) on April 16, 1991, and concluded May 7. In accordance with our mining and reclamation plan we are submitting the following information regarding observation of surface disturbance during second mining.

During that second mining Genwal Coal Company conducted subsidence monitoring on a weekly basis. During this observation, no visual subsidence was observed.

Should you have any questions or need additional information, please contact me at 687-9813.

Sincerely,

GENWAL COAL COMPANY



Randal J Ralphs  
Surface Foreman

tr

## SUBSIDENCE MONITORING

Started Second Mining April 16, 1991.

April 19 No visual subsidence was noted

April 26 No visual subsidence was noted

May 1 No visual subsidence was observed

May 7 No visual subsidence noted from roadway

May 7 Completed second mining

June 18 No second mining conducted since May 7, 1990. Visual inspection made from road in Crandall Canyon and Huntington Canyon. Also a visual observation was made while walking in no name canyon while collecting water samples. No visual subsidence observed at that time.