

GENWAL COAL COMPANY**RECEIVED**

NOV 15 1991

DIVISION OF
OIL GAS & MINING

November 14, 1991

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West, North Temple
Salt Lake City, Utah 84180-1203

RE: Permit # ACT 015-032
Genwal Coal Company
Violation 91-15-2-3
Violation 2 of 3
Surface Facility Map (Plate 3-1)

Dear Mr. Haddock:

Please find enclosed four (4) copies of a current, accurate map of the surface facilities at Genwal Coal Company Crandal Canyon Mine. Once the map meets your approval replace these newly submitted maps with the currently approved ones.

The disturbed area and permitted area boundaries have been corrected. The facility locations, legend, scale, north arrow, Crandal Creek channel, and other surface features are accurate and have not been changed. The contours on the South side of Crandal Creek off our permitted area have been added for your convenience. The contour interval remains at a 10' interval. A 2' contour interval is unreasonable in an area as steep as Crandal Canyon and would result in a map that was not legible. Should you still require a 2' contour interval let me know and I will supply you with a map showing 2' contours.

The above map was prepared and verified by me or under my direct supervision and should satisfy the requirements for abatement of violation 91-15-2-3 violation 2 of 3.

If you have any questions or comments please call.

Sincerely;

R. Jay Marshall
R. Jay Marshall P.E.
Chief Engineer
Genwal Coal Company